





955 -959 953 958 1,202 951 1111111111 1000-FIG. 12 950

	With Spar	Without Spar
Glass Ceramic max Z-deflection (mils)	0.98	1.81
Glass Ceramic max S1 Stress (MPa)	~42	~68
Cinch button load range (gm/10)	134–213	119–200
Thermal Paste Strain (% change)	3.0-6.6	1.2–27.8

FIG. 14